



## HP-6108-000 Return Air Temperature Sensor Installation


Issue Number: CSB1169

Date: 11.12.2020

Dear Customer,

If the filter is required to be replaced within Grayson Part Number HP-6108-000, please ensure that the Return Air Temperature Sensor (RTS) is replaced and installed as prescribed in the imagery and instructions below.

- Insert the foam filter (HP-6108-016) between the evaporator and the filter frame keeping the RTS air temperature sensor in front of it as shown.



A poor installation of the sensor can lead to a GTS Service Engineer being called out to investigate erratic heating performances. If it is confirmed that the performance issues reported were as a result of a poor installation, this is non warrantable and therefor chargeable.

To avoid unnecessary callout and cost, please ensure sensors are installed correctly and for further advice do not hesitate in contacting Grayson.